SET safe SET fuse Q Series




Features

- Non-Resettable
- High Accuracy of Functioning Temp.
- High Surge Capacity
- RoHS & REACH Compliant

Structure Diagrams

Dimensions (mm)

Radial



Description

The Direct Current Thermal-Link Alloy Type (DC-ATCO) is defined as a non-resettable protective device functioning one time only. It is widely used in electrical equipment. ATCO is mainly consist of fusible alloy, flux resin, case, sealant and lead wires. Normally, fusible alloy is jointed to the two lead wires. Under abnormal conditions, when the temp. reaches to the fusing temp. of ATCO, the fusible alloy melts and quickly retracts to the two lead wire ends with the aid of the flux resin and disconnects the circuit completely.


SETsafe | SETfuse Direct Current Thermal-Link Alloy Type (DC-ATCO) Q series Rated Functioning Temp. from 102 °C to 136 °C, Rated Current: 25A, safety certification Includes UL, cUL, TUV, CCC, PSE, and complies with RoHS and REACH.

Applications

- Surge Protective Devices
- Power Strips
- Lamps
- Switched-Mode Power Supplies
- Home Electrical Appliances
- Batteries

Marking

Radial (Color for reference only)



Remark: The Date Code means Year and quarter: A stands for 2000, B stands for 2001 and 01 stands for the first quarter, 02 stands for the second quarter, and so on.

$L = L_1 = W = T = d = F$ $11.5 \pm 0.5 = 50.0 \pm 2.0 = 10.8 \pm 0.5 = 4.8 \pm 0.2 = 1.60 \pm 0.05 = 6.6 \pm 0.8$

+86-592-571-5838 www.SETfuse.com www.SETsafe.com E-mail : sales@SETfuse.com

Customization

- Other Temp.
- The Length of Lead Wires
- Leads Forming Types

SET safe | SET fuse

DC-ATCO Direct Current Thermal-Link (Alloy Type)

Specifications

		Model	Fusing Temp.	T _h	T _m	I _r	Ur	<i>I</i> n 8 / 20 μs (15 Times)	<i>I</i> _{max} 8 / 20 μs (1 Time)	FU ®	c AV ®		A starting the starting of the		RoHS REACH
			(°C)	(°C)	(°C)	(A)	(V)	(kA)	(kA)	UL	cUL	τυν	PSE	ссс	
							AC 250			•	•	0	•	0	•
(<i>T</i> _f) °C	136	Q136	121 + 2	102	200	25	AC 300	15	30	•	•	0	•	0	•
Ľ)	130	Q136	131 ± 2	102	200	25	AC 400		30	0	0	•	•	•	•
Rated Functioning Temp.							DC 120			0	0	•	0	•	•
	125	Q125	121 ± 2		200	25	AC 250	15	30	0	0	0	•	0	•
ing				90			AC 400			0	0	•	•	•	•
tion							DC 120			0	0	•	0	•	•
nci							AC 250		30	•	•	0	•	0	•
ц Б	115	Q115	111 ± 2	82	200	25	AC 300	15		•	•	0	•	0	•
ate	115	QTIS	11112	02	200	25	AC 400	15	50	0	0	•	•	•	•
Ř							DC 120			0	0	•	0	•	•
						25	AC 250	12		0	0	0	•	0	•
	102	Q102	98 ± 2	66	200		AC 400		25	0	0	•	•	•	•
							DC 120			0	0	•	0	•	•

Note:

1: "●"Means certificated, "○"Means non-certificated.

2: RoHS & REACH Compliant .



SET safe SET fuse

Agency Information

Agency Symbol	Standards	The File No. and certification No. obtained by SETsafe SETfuse
	UL 60691	E214712
c RN ®	CAN-CSA-E60691	E214712
A	EN 60691	R50259029
PS E	J60691	JET2121-32001-2032、JET2121-32001-2033
	GB 9816.1	2020980205000180

Soldering

Hand-Soldering


- 1. Soldering should be carried out according to Table T-1.
- 2. The thermal element of ATCO is fusible alloy with low melting point, which is jointed with ATCO lead wires. Improper soldering operation (too high soldering temp., too long soldering time, too short lead wire etc.) may transfer more heat to the thermal element and ATCO may open in advance.
- 3. When soldering conditions are more severe than those listed in Table T-1, a heat sink fixture should be used between soldering point and ATCO body.
- 4. When soldering, please do not pull / push or twist ATCO body or lead wires.
- After soldering, let it naturally cool for longer than 20 seconds. During cooling, never move the ATCO body or lead wires.

TABLE T-1 Hand-Soldering Time

Rated Functioning Temp.	Max. Allowable Soldering Time for Different Lead Wire Length (Fig.T-1)													
(<i>T</i> _f)	L _s			L _s	Time)	L _s	Tim	Temp.					
	Length -	Tinned Copper Wire	CP Wire	Length -	Tinned Copper Wire	CP Wire	Length	Tinned Copper Wire	CP Wire					
(°C)	(mm)	(s)	(s)	(mm)	(s)	(s)	(mm)	(s)	(s)	(°C)				
102 to 115	10	1 ^a	4	20	2	5	30	3	6					
116 to 135	10	1 ^a	4	20	3	6	30	5	8	400				
136 to 150	10	3	6	20	5	8	30	5	8	1				

Note:

a: Auxiliary Heat Sink Fixture is Required to Avoid ATCO Cutting off Unexpectedly.



ATCO Body


SET safe SET fuse

Wave Soldering

The wave soldering parameters as Table T-2, for reference only, when ATCO is for practice use, you need to do some validation experiments. For example, using X-RAY to see the fusible alloy of ATCO whether damage after wave soldering.

TABLE T-2 Wave Soldering Parameters Setting


Rated Functioning Temp.	Whe	-		ng Temp. re is Different	Preheating Time (t ₁)	Max. Wave Soldering	Dwelling Time (t ₂)	Cooling Time (t ₃)	
(<i>T</i> _f)	L _s Length	Preheating Temp.	L _s Preheating Length Temp.			Temp.			
(°C)	(mm)	(°C)	(mm)	(°C)	(s)	(°C)	(s)	(s)	
102 to 130									
131 to 150	20 80 30			90	< 60	≤ 260	≤ 3	≤ 10	



SET safe | SET fuse


Product Temp.-Time Curve (Reference)

The Temp.-Time Curve of Thermal-Link in different temp. oil bath.



Product Current-Time Curve (Reference)

The Current-Time Curve shows functioning time at multi-times rated current at room temperature 25 ± 2 °C.






Q Series


Packaging Information

Bulk

Item	PE Bag	PE Bag	Carton								
Dimensions (mm)	135 × 85	190 × 180	440 × 300 × 260								
Quantity (PCS)	30	180	9000								
Gross Weight (kg)	Gross Weight (kg)										



Part Numbering System



SET safe SET fuse

Q Series

SET safe | SET fuse

Glossary

Item	Description
	Thermal-Link
тсо	A non-resettable device incorporating a THERMAL ELEMENT which will open a circuit once only when exposed for a sufficient length of time to a temperature in excess of that for which it has been designed.
	— (GB 9816.1)
	Alloy Thermal-Link
ATCO	Alloy Type Thermal-Link, Alloy is the thermal element. — (GB 9816.1)
Tf	Rated Functioning Temp. The temperature of the Alloy Thermal-Link which causes it to change the state of conductivity with a detection current up to 10 mA as the only load.
	— (GB 9816.1
	Tolerance: <i>T</i> _f °C (GB 9816.1, EN 60691, K60691). Tolerance: <i>T</i> _f ± 7 °C (J60691).
Fusing Temp.	Fusing Temp. The temperature of the Alloy Thermal-Link which causes it to change its state of conductivity is measured with silicone oil bath in which the temperature is increased at the rate of 0.5 °C to 1 °C / minute, with a detection current up to 10 mA as the only load.
	— (GB 9816.1
	Holding Temp.
T _h	The Maximum temperature at which a Alloy Thermal-Link will not change its state of conductivity when conducting rated
	current for 168 hours. — (GB 9816.1
	Maximum Temp. Limit
T _m	The temperature of the Alloy Thermal-Link stated by the manufacturer, up to which the mechanical and electrical properties
	of the Alloy Thermal-Link having changed its state of conductivity, will not be impaired for a given time. — (GB 9816.1
	Rated Current
<i>I</i> r	The current used to classify a Alloy Thermal-Link, which is the Maximum current that Alloy Thermal-Link allows to carry and is able to cut off the circuit safely.
	— (GB 9816.1
U _r	Rated Voltage The voltage used to classify a Alloy Thermal-Link, which is the Maximum voltage that Alloy Thermal-Link allows to carry and is able to cut off the circuit safely.
	— (GB 9816.1
	Nominal Discharge Current
I _n	Being able to withstand 15 peak currents of waveform 8/20 μs to test the product's durability of withstanding pulse current.
	— (UL 1449)
	Max. Discharge Current
I _{max}	Being able to withstand 1 peak current of waveform 8/20 µs to test max. pulse current that the product can withstand.
	— (UL 1449

SET safe | SET fuse

Q Series



ATTENTION

Usage

- 1. When atmosphere pressure is from 80 kPa to 106 kPa, the related altitude shall be from 2000 meters to 500 meters.
- 2. Operating voltage less than rated voltage of ATCO, operating current less than rated current of ATCO.
- 3. Do not touch the ATCO body or lead wires directly when power is on, to avoid burn or electric shock.

Replace

ATCO is a non-repairable product. For safety sake, it shall be replaced by an equivalent ATCO from the same manufacturer, and mounted in the same way.

Storage

Do not store the ATCO at the high temp., high humidity or corrosive gas environment, avoid influencing the solder-ability of the lead wires, the product shall be used up within 1 year after receiving the goods.

Installation

Make Sure the Temp. of Installation Position.

- 1. It is recommended that a dummy ATCO with inbuilt thermo-couple shall be used to determine the proper temp.
- 2. The terminal product should be tested to ensure that potential abnormal conditions do not cause ambient temp. to exceed the T_m of the ATCO.
- 3. Mount the ATCO at the location where temp. rises evenly.

Installation position of mechanical performance requirements.

- 1. Do not locate the ATCO in a place where severe vibration always occurs.
- 2. Ensure that the lead wire is long enough, and avoid actions such as press, tensile or twist.
- 3. The seal or body of ATCO must not be damaged, burned or over heated.



Mechanical Connection

Riveting

- 1. Choose small resistivity riveting material and be riveted.
- 2. A flexible lead or lead with low resistance should be used to rivet the ATCO.
- 3. Contact resistance should be minimal, large contact resistance will lead to higher temp., ATCO Functioning in advance.

Crimping

- 1. Choose small resistivity crimping material and be crimped.
- 2. A flexible lead or lead with low resistance should be used to rivet the ATCO.
- 3. Contact resistance should be minimal, large contact resistance will lead to higher Temp., ATCO Functioning in advance.

Lead Wire Forming

- 1. If lead wire has to be bent, please pay attention to the distance between body and bending point. Refer to Table T-3.
- 2. When bending leads, please use pincher or similar tools to fix the product as shown in Fig.T-2, to avoid damaging the product.
- 3. During forming and mounting, lead wire should not be cut, nicked, bent sharply, to avoid breaking the product.
- 4. Tangential forces on the leads must be avoided (i.e. pushing or pulling on the leads at angle to ATCO body) as such forces may damage the seal of ATCO.




TABLE T-3 Distance between Body and Bending Point


	d	(mm)	< 1.0	1.0 - 1.2	> 1.2
Circular lead	L _b	(mm)	≥ 3	≥ 5	≥ 10


SET safe SET fuse

Leads Forming Types

The below leads forming is for reference, more leads forming can be customized.

Radial





Direct Current Thermal-Link Alloy Type (DC-ATCO) Features & Model List Overview

ETsafe **Q** Series

SET


fuse

Direct Current Thermal-Link (Alloy Type)

Õ

ATC

Ô



DC

ATC

Ô


ET safe SET

fuse

Q Series

Direct Current Thermal-Link Alloy Type (DC-ATCO) Features & Model List Overview

.com



Direct Current Thermal-Link Alloy Type (DC-ATCO) Features & Model List Overview


Direct Current Thermal-Link (Alloy Type)

Õ

ATCO

ET safe **SET** fuse

Q Series



DC

ATC

Ô

ET safe SET fuse

Q Series

Direct Current Thermal-Link Alloy Type (DC-ATCO) Features & Model List Overview

.com

															/	N	
230	0	0	0	0	0	0	0	0	0	0	0	ADN230B-NDZ^	ADN230B-PDZ^	0	ADN230B-QBZ^		
	XG31*	KG31*			C31*		B31*		H31*			0	0	ADN205B-NDZ^	0		
205	XG32*	KG32*			C33*		B32*		H32*								
200	0																
187	0																
160	XG16*	KG16*				B16*											
150	XG7*	KG7*	C7^	C7*		B7^*		H7^*		V7^*							
145	XG6*	KG6*	C6^	C6*		B6^*		H6^*		V6^*							
139	0		C13^	C13*		B13^*		H13^*		V13^*							
136	XG9*	KG9*	C9^	C9*		B9^*		H9^*		V9^*							
135	XG5*	KG5*	C5^	C5*		B5^*		H5^*		V5^*						S	
133	XG8*	KG8*	C8^	C8*		B8^*		H8^*		V8^*						Model	
130	XG4*	KG4*	C4^	C4*		B4^*		H4^*		V4^*						e	
125	XG3^*	KG3^*	C3^	C3*		B3^*				V3^*							
123	0																
120	0																
115	XG2^*	KG2^*	C2^	C2*		B2^*		H2^*		V2^*							
105	0																
	XG1^*	KG1^*		C1^*	C1*	B1^*	B1*	H1^*	H1*	V1^*	V1*						
97	0				C21^*		B21^*		H21^*		V21^*						
93	0																
86	XG18^*	KG18^*		C18^*	C18*	B18^*	B18*	H18^*	H18*	V18^*	V18*						
) XG0*	KG0*	0	C0*	0	B0^*	B0*	H0^*	H0*	V0^*	V0*	0	0	0	0	\rightarrow	
) rrent	3	2	7	Ę	5	3			2		1	50	55	50	80	Í	
C)^ Itage	60					50						49	4	.8	24		
C)*	2	50	0	250	125	250	125	250	125	250	125		 O				
Product Structure																	
	200 187 160 150 145 139 136 135 133 130 125 123 120 115 102 97 93 86 76 0 76 76 0 76 160 176 176 176 176 176 176 176 176 176 176 176 176	221 XG31* 205 XG32* 200 0 187 0 160 XG16* 150 XG7* 145 XG6* 139 0 136 XG9* 135 XG5* 133 XG4* 125 XG3^* 120 0 115 XG2^* 102 XG1^* 97 0 93 0 86 XG18^* 76 XG0* 0:rrent 3 134 XG0* 0:rrent 3 0:rrent 3 0:rrent 2 Jurce	221 XG31* KG31* 205 XG32* KG32* 200 O O 187 O O 187 O O 187 O O 187 XG16* KG16* 150 XG7* KG7* 145 XG6* KG6* 139 O O 136 XG9* KG9* 135 XG5* KG5* 133 XG4* KG4* 135 XG2^* KG3* 130 XG4* KG4* 123 O O 124 XG2^* KG2** 135 XG2** KG2** 120 O O 121 O O 122 XG1** KG1** 97 O O 93 O O 94 XG0* KG0* 97 3 2 97 G0 O 97 G0 O <th>221 XG31* KG31* O 205 XG32* KG32* O 200 O O O 187 SG6* KG1* C7^ 145 XG6* KG6* C6^ 130 XG9* KG9* C9^ 135 XG8* KG8* C8^ 130 XG4* KG4* C4^ 125 XG2^* KG2^* C2^ 130 XG4* KG4* C4^ 121 O O O 122 XG1^* KG2^* C2^ 105 XG2* KG1* O 120 O O O 121 XG1^* KG1^* O 97 O O O 97 O O O 93 O O <t< th=""><th>221 XG31* KG31* O O 205 XG32* KG32* O O 200 O O O O 187 O O O O 160 XG16* KG16* O O 150 XG7* KG7* C7^ C7* 145 XG6* KG6* C6A C6* 139 O O C13^ C13* 136 XG9* KG9* C9^ C9* 135 XG8* KG8* C8A C8* 130 XG4* KG4* C4^ C4* 125 XG2A* KG2A* C2^ C2* 120 O O O O 121 O O O O 120 O O O O 121 XG2A* KG2A* C2^ C2* 122 XG3A* KG1A* O C1A* 97 O O O O</th><th>221 XG31* KG31* O C31* 205 XG32* KG32* O C33* 200 O O O O O 187 O O O O O 160 XG16* KG16* C O O 150 XG7* KG7* C7^ C7* O 145 XG6* KG6* C6A C6* O 130 XG9* KG9* C9A C9* O 133 XG8* KG8* C8A C8* O 133 XG8* KG8* C3A C3* O 133 XG8* KG8* C3A C3* O 133 XG4* KG4* C4A C4* O 123 O O O O O 124 O O O O O 125 XG3A* KG1A* C2A C2* O 126 XG1A* KG1A* O C1A*</th><th>221 XG31* KG31* O C31* O 205 XG32* KG32* O C33* O 200 O O O O O O 187 O O C13* C1* O B1** 145 XG6* KG6* C6A C6* O B6** 138 XG9* KG9* C9A C9* O B9** 135 XG5* KG5* C5* O B5** 133 XG4* KG4* C4^A C4* O B4** 125 XG3* KG3** C3* C3* D D 120 O O O O O O 121</th><th>221 XG31* KG31* O C31* O B31* 205 XG32* KG32* O O C33* O B32* 200 O<th>221 XG31* KG31* 0 0 C31* 0 B31* 0 205 XG32* KG32* 0 0 0 0 0 0 200 0 0 0 0 0 0 0 0 187 0 0 0 0 0 0 0 0 0 180 XG1* KG1* C7A C7* 0 B7A* 0 H7A* 145 XG6* KG6* C6A C6* 0 B6A* 0 H6A* 139 0 C13^A C13* 0 B13** 0 H9A* 135 XG5* KG5* C5^A C5* 0 B5** 0 H9** 133 XG8* KG8* C8* C8* 0 B8** 0 H4** 133 XG3* KG3** C3^A C3* 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0</th><th>221 XG31* KG31* O C31* O B31* O H31* 205 XG32* KG32* O C C33* D B32* O H32* 200 O <td< th=""><th>221 XG31* KG31* C C C31* C B31* H31* C 205 XG32* KG32* C C C33* B32* H32* C 200 C <td< th=""><th>221 XG31* KG31* G G C31* G B31* G H31* G G 205 XG32* KG32* G G C33* B32* H32* G G 200 G G G G G G G G G G 187 G</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 AB1* 0 0 0 0 ADN205B-MD2* 205 XG32* KG32* 0 0 C33* 0 B32* 0<!--</th--><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0 0 0 0 0 0 0 205 XG32* KG32* C 0</th></th></td<></th></td<></th></th></t<></th>	221 XG31* KG31* O 205 XG32* KG32* O 200 O O O 187 SG6* KG1* C7^ 145 XG6* KG6* C6^ 130 XG9* KG9* C9^ 135 XG8* KG8* C8^ 130 XG4* KG4* C4^ 125 XG2^* KG2^* C2^ 130 XG4* KG4* C4^ 121 O O O 122 XG1^* KG2^* C2^ 105 XG2* KG1* O 120 O O O 121 XG1^* KG1^* O 97 O O O 97 O O O 93 O O <t< th=""><th>221 XG31* KG31* O O 205 XG32* KG32* O O 200 O O O O 187 O O O O 160 XG16* KG16* O O 150 XG7* KG7* C7^ C7* 145 XG6* KG6* C6A C6* 139 O O C13^ C13* 136 XG9* KG9* C9^ C9* 135 XG8* KG8* C8A C8* 130 XG4* KG4* C4^ C4* 125 XG2A* KG2A* C2^ C2* 120 O O O O 121 O O O O 120 O O O O 121 XG2A* KG2A* C2^ C2* 122 XG3A* KG1A* O C1A* 97 O O O O</th><th>221 XG31* KG31* O C31* 205 XG32* KG32* O C33* 200 O O O O O 187 O O O O O 160 XG16* KG16* C O O 150 XG7* KG7* C7^ C7* O 145 XG6* KG6* C6A C6* O 130 XG9* KG9* C9A C9* O 133 XG8* KG8* C8A C8* O 133 XG8* KG8* C3A C3* O 133 XG8* KG8* C3A C3* O 133 XG4* KG4* C4A C4* O 123 O O O O O 124 O O O O O 125 XG3A* KG1A* C2A C2* O 126 XG1A* KG1A* O C1A*</th><th>221 XG31* KG31* O C31* O 205 XG32* KG32* O C33* O 200 O O O O O O 187 O O C13* C1* O B1** 145 XG6* KG6* C6A C6* O B6** 138 XG9* KG9* C9A C9* O B9** 135 XG5* KG5* C5* O B5** 133 XG4* KG4* C4^A C4* O B4** 125 XG3* KG3** C3* C3* D D 120 O O O O O O 121</th><th>221 XG31* KG31* O C31* O B31* 205 XG32* KG32* O O C33* O B32* 200 O<th>221 XG31* KG31* 0 0 C31* 0 B31* 0 205 XG32* KG32* 0 0 0 0 0 0 200 0 0 0 0 0 0 0 0 187 0 0 0 0 0 0 0 0 0 180 XG1* KG1* C7A C7* 0 B7A* 0 H7A* 145 XG6* KG6* C6A C6* 0 B6A* 0 H6A* 139 0 C13^A C13* 0 B13** 0 H9A* 135 XG5* KG5* C5^A C5* 0 B5** 0 H9** 133 XG8* KG8* C8* C8* 0 B8** 0 H4** 133 XG3* KG3** C3^A C3* 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0</th><th>221 XG31* KG31* O C31* O B31* O H31* 205 XG32* KG32* O C C33* D B32* O H32* 200 O <td< th=""><th>221 XG31* KG31* C C C31* C B31* H31* C 205 XG32* KG32* C C C33* B32* H32* C 200 C <td< th=""><th>221 XG31* KG31* G G C31* G B31* G H31* G G 205 XG32* KG32* G G C33* B32* H32* G G 200 G G G G G G G G G G 187 G</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 AB1* 0 0 0 0 ADN205B-MD2* 205 XG32* KG32* 0 0 C33* 0 B32* 0<!--</th--><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0 0 0 0 0 0 0 205 XG32* KG32* C 0</th></th></td<></th></td<></th></th></t<>	221 XG31* KG31* O O 205 XG32* KG32* O O 200 O O O O 187 O O O O 160 XG16* KG16* O O 150 XG7* KG7* C7^ C7* 145 XG6* KG6* C6A C6* 139 O O C13^ C13* 136 XG9* KG9* C9^ C9* 135 XG8* KG8* C8A C8* 130 XG4* KG4* C4^ C4* 125 XG2A* KG2A* C2^ C2* 120 O O O O 121 O O O O 120 O O O O 121 XG2A* KG2A* C2^ C2* 122 XG3A* KG1A* O C1A* 97 O O O O	221 XG31* KG31* O C31* 205 XG32* KG32* O C33* 200 O O O O O 187 O O O O O 160 XG16* KG16* C O O 150 XG7* KG7* C7^ C7* O 145 XG6* KG6* C6A C6* O 130 XG9* KG9* C9A C9* O 133 XG8* KG8* C8A C8* O 133 XG8* KG8* C3A C3* O 133 XG8* KG8* C3A C3* O 133 XG4* KG4* C4A C4* O 123 O O O O O 124 O O O O O 125 XG3A* KG1A* C2A C2* O 126 XG1A* KG1A* O C1A*	221 XG31* KG31* O C31* O 205 XG32* KG32* O C33* O 200 O O O O O O 187 O O C13* C1* O B1** 145 XG6* KG6* C6A C6* O B6** 138 XG9* KG9* C9A C9* O B9** 135 XG5* KG5* C5* O B5** 133 XG4* KG4* C4^A C4* O B4** 125 XG3* KG3** C3* C3* D D 120 O O O O O O 121	221 XG31* KG31* O C31* O B31* 205 XG32* KG32* O O C33* O B32* 200 O <th>221 XG31* KG31* 0 0 C31* 0 B31* 0 205 XG32* KG32* 0 0 0 0 0 0 200 0 0 0 0 0 0 0 0 187 0 0 0 0 0 0 0 0 0 180 XG1* KG1* C7A C7* 0 B7A* 0 H7A* 145 XG6* KG6* C6A C6* 0 B6A* 0 H6A* 139 0 C13^A C13* 0 B13** 0 H9A* 135 XG5* KG5* C5^A C5* 0 B5** 0 H9** 133 XG8* KG8* C8* C8* 0 B8** 0 H4** 133 XG3* KG3** C3^A C3* 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0</th> <th>221 XG31* KG31* O C31* O B31* O H31* 205 XG32* KG32* O C C33* D B32* O H32* 200 O <td< th=""><th>221 XG31* KG31* C C C31* C B31* H31* C 205 XG32* KG32* C C C33* B32* H32* C 200 C <td< th=""><th>221 XG31* KG31* G G C31* G B31* G H31* G G 205 XG32* KG32* G G C33* B32* H32* G G 200 G G G G G G G G G G 187 G</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 AB1* 0 0 0 0 ADN205B-MD2* 205 XG32* KG32* 0 0 C33* 0 B32* 0<!--</th--><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0 0 0 0 0 0 0 205 XG32* KG32* C 0</th></th></td<></th></td<></th>	221 XG31* KG31* 0 0 C31* 0 B31* 0 205 XG32* KG32* 0 0 0 0 0 0 200 0 0 0 0 0 0 0 0 187 0 0 0 0 0 0 0 0 0 180 XG1* KG1* C7A C7* 0 B7A* 0 H7A* 145 XG6* KG6* C6A C6* 0 B6A* 0 H6A* 139 0 C13^A C13* 0 B13** 0 H9A* 135 XG5* KG5* C5^A C5* 0 B5** 0 H9** 133 XG8* KG8* C8* C8* 0 B8** 0 H4** 133 XG3* KG3** C3^A C3* 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	221 XG31* KG31* O C31* O B31* O H31* 205 XG32* KG32* O C C33* D B32* O H32* 200 O <td< th=""><th>221 XG31* KG31* C C C31* C B31* H31* C 205 XG32* KG32* C C C33* B32* H32* C 200 C <td< th=""><th>221 XG31* KG31* G G C31* G B31* G H31* G G 205 XG32* KG32* G G C33* B32* H32* G G 200 G G G G G G G G G G 187 G</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 AB1* 0 0 0 0 ADN205B-MD2* 205 XG32* KG32* 0 0 C33* 0 B32* 0<!--</th--><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0 0 0 0 0 0 0 205 XG32* KG32* C 0</th></th></td<></th></td<>	221 XG31* KG31* C C C31* C B31* H31* C 205 XG32* KG32* C C C33* B32* H32* C 200 C <td< th=""><th>221 XG31* KG31* G G C31* G B31* G H31* G G 205 XG32* KG32* G G C33* B32* H32* G G 200 G G G G G G G G G G 187 G</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0</th><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 AB1* 0 0 0 0 ADN205B-MD2* 205 XG32* KG32* 0 0 C33* 0 B32* 0<!--</th--><th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0 0 0 0 0 0 0 205 XG32* KG32* C 0</th></th></td<>	221 XG31* KG31* G G C31* G B31* G H31* G G 205 XG32* KG32* G G C33* B32* H32* G G 200 G G G G G G G G G G 187 G	221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0	221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0	221 XG31* KG31* 0 0 C31* 0 B31* 0 AB1* 0 0 0 0 ADN205B-MD2* 205 XG32* KG32* 0 0 C33* 0 B32* 0 </th <th>221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0 0 0 0 0 0 0 205 XG32* KG32* C 0</th>	221 XG31* KG31* 0 0 C31* 0 B31* 0 H31* 0 0 0 0 0 0 0 205 XG32* KG32* C 0	

SET safe SET fuse

Q Series

Direct Current Thermal-Link Alloy Type (DC-ATCO) Features & Model List Overview